





X144D e-FlowMeter Quick Start Programming

SETTINGS – VALVE (Adjust meter size and valve size parameters)

Note: Stylus Pen Recommended for Touch Screen Programming



From Flow Rate or Sensor Frequency screen, select  to access **Settings** menu.



Select **VALVE** then **YES** to configure meter size




Select correct METER size from chart below

X144D Sizes	1			2		3		4						
Full Port Valve Sizes	2	2-1/2	3	4	6	8	10	12	14	16	18	20	24	30
Reduced Port Valve Sizes	4	4	4	6	8	10	12	14	16	18	20	24	CF	CF



Save configuration


SETTINGS – OUTPUT (Adjust Gain, mA Scaling, mA Filtering, Pulse Weight, and 4-20mA Output Test)




Select **OUTPUT** then **YES** to configure output.



Default Gain is 1.00. Use arrow keys to adjust gain to desired value. Increasing or decreasing value offsets factory calibration. Select **NEXT** to continue.



Use arrow keys to set 20mA Full Scale Output. Match 20mA value to customer display and/or SCADA. Select **NEXT** to continue.



Default Filter is 4.00. Use arrow keys to increase or decrease filtering of 4-20mA signal. The higher the average filter strength, the longer the averaging time. Select **NEXT** to continue.




X144D e-FlowMeter

Quick Start Programming


SETTINGS – OUTPUT (Continued)




Default Pulse Weight is 1.00. Use arrow keys to increase or decrease Pulse Weight.
Flow Rate = Number of Pulses x Pulse Weight / Time. Select **NEXT** to continue.




This setting is used to set a minimum flow reading that is displayed on screen before displaying zero flow. This is used when noise or vibration is causing erratic low flow readings when there is no flow. Select **NEXT** to continue.




To save changes select **YES** .
To discard changes and advance to next menu select **NO** .



To test 4 and 20mA outputs select **YES** . To return to settings menu select **NO** .



In this menu, a 4mA output signal is generated. To calibrate 4mA output to external device, use arrow keys to increase or decrease 4mA output. A Digital Multimeter to measure 4mA output.
Select **NEXT** to continue to 20mA test.




In this menu, a 20mA output signal is generated. To calibrate 20mA output to external device, use arrow keys to increase or decrease 20mA output. A Digital Multimeter to measure 20mA output. Select **EXIT** to return to Settings Menu.




X144D e-FlowMeter

Quick Start Programming


SETTINGS – DISPLAY – UNITS



Select **DISPLAY** to configure display settings.




Select **UNITS** then **YES** to configure units settings.



Select desired flow units for flow rate display. Select **YES** to save changes or **NO** to discard changes and return to **DISPLAY** menu.

DISPLAY – DECIMAL



Select **DECIMAL** then **YES** to configure decimal settings.




Use arrow key to select decimal point for flow rate home screen. Select **YES** to save changes or **NO** to discard changes and return to **DISPLAY** menu.

DISPLAY – OTHER – BRIGHTNESS



Select **OTHER** then **BRIGHTNESS** to configure screen brightness.



Use arrow keys to select desired brightness. Select **SAVE** to save changes and return to **OTHER** menu.




X144D e-FlowMeter Quick Start Programming

OTHER – TIMEOUT



Select **TIMEOUT** to configure screen sleep.



Use arrow keys to select desired duration before screen goes into sleep mode.

Select **SAVE** to save changes and return to **OTHER** menu. Use Timeout if powering from battery source to save power consumption. If screen Timeout is set to 00 minutes, display will not go into sleep mode.

OTHER – RESET



Select **RESET** → **YES** to initiate Touch Screen Calibration.

Select **NO** to return to **OTHER** menu.



Touch RED dots as they appear on touch screen.



Successful Touch Screen Calibration will result in message **Calibration Done**.



Touch **Calibration Done** to reboot and return to home screen. If message **Calibration Failed!** is displayed, touch **Calibration Failed!** and repeat Touch Screen Calibration until successful calibration.



N-X144D QS-Programming
(R-03/2018)

1701 Placentia Avenue • Costa Mesa, CA 92627
800-942-6326 • Fax: 949-548-5441 • Web Site: cla-val.com • E-mail: info@cla-val.com

CLA-VAL CANADA
4687 Christie Drive
Beamsville, Ontario
Canada L0R 1B4
Phone: 905-563-4963
Fax: 905-563-4040
E-mail: sales@cla-val.ca

CLA-VAL EUROPE
Chemin des Mésanges 1
CH-1032 Romanel/
Lausanne, Switzerland
Phone: 41-21-643-15-55
Fax: 41-21-643-15-50
E-mail: cla-val@cla-val.ch

CLA-VAL UK
Dainton House, Goods Station Road
Tunbridge Wells
Kent TN11 2 DH England
Phone: 44-1892-514-400
Fax: 44-1892-543-423
E-mail: info@cla-val.co.uk

CLA-VAL FRANCE
Porte du Grand Lyon 1
ZAC du Champ du Pérrier
France - 01700 Neyron
Phone: 33-4-72-25-92-93
Fax: 33-4-72-25-04-17
E-mail: cla-val@cla-val.fr

CLA-VAL PACIFIC
45 Kennaway Road
Woolston, Christchurch, 8023
New Zealand
Phone: 64-39644860
www.cla-valpacific.com
E-mail: info@cla-valpacific.com